



March 11, 2020

Sent Via E-mail

Request for Tender
EP102-2020

ADDENDUM #1

HIGH VOLTAGE FEEDERS REPLACEMENT

CLOSING: 3:00 PM ON Monday, March 23, 2020

Please refer to the above RFT document in your possession and be advised of the following:

Part A: Clarification

1. There are several events at Exhibition Place including move in and move out dates when work cannot be done on this project. General Construction Schedule Restrictions are included with this Addendum.
2. The Duct Bank Inspection Report is included with this Addendum for bidders' information.
3. In the tender documents package whereas the term "Exhibition Place of Toronto" should be read as Exhibition Place.
4. Addendum 1 – Part 2 Construction Agreement revised schedule A is included with this Addendum.
5. Addendum 1 – Part 5 Pricing Form is included with this Addendum.

Part B: Questions and answers

Q1. To be able to bid on this tender does a company have to be unionized?

A1. Please refer Schedule F, Workers Rights is included with this Addendum for additional clarification.

- Q2. Is there space available that can be used for a trailer for storage of supplies and equipment?
- A2. Contractor will be assigned a location for parking a trailer
- Q3. Is an environmental assessment the responsibility of the supplier to complete?
- A3. See part 4 form A and schedule F
- Q4. Is GEO technical reporting and testing required?
- A4. No, this will be decided during construction
- Q5. Will there be any additional drawings provided for the tendering stage?
- A5. No
- Q6. Is there a specific cable supplier that is required to be used?
- A6. See specifications.
- Q7. Do bidders have to have COR?
- A7. Bidders who qualify with experience in similar projects will be considered.
- Q8. What is the total distance of the feeders?
- A8. 1,300 meters
- Q9. How many manholes are there?
- A9. There are 20 manholes.
- Q10. What kind of cables are they?
- A10. They are PILC cables.
- Q11. Is there an allowance for collapsed ducts or asbestos remediation?
- A11. There will be a contingency fund to deal with this.
- Q12. Were all manholes inspected?
- A12. 18 of 19 were inspected and found to be in good condition. The 19th is located under TTC tracks and was not inspected.

Q13. Please confirm the address to be used for Bid Bond, Performance, Labour and Material documentation?

A13. The address to be used for Bid Bond, is the same as the submission address:
General Services Building
Capital Works
2 Manitoba Dr.
Toronto, ON
M6K 3C3

The address for the Performance, Labour and Material documentation will be provided after the contract is awarded.

Should you have any questions regarding this addendum, contact the undersigned at 416-263-3628 or via e-mail at purchasing@explace.on.ca

Please attach this Addendum to your submission and be governed accordingly. All other aspects of the RFT remain the same.

Sincerely,

T. Lynn Miller
Purchasing Manager